## **AT&T FiberLine Installation Manual**


## Multimedia Box

## AT&T P/N 53M2016012N-WT51


## **Optical Fiber Cabling**




Step 1: Open the Box.



Step 2:
Break off the cable entry
from the cover and from the
back box.



Step 3: Tie the cable to the box and wrap the fibers around the center 2~3 times as shown.




Step 4: Splice suitable pigtails to the cable fibers, cover the spliced section with the protection sleeve and place it in the rubber retainer as shown.



Step 5: Insert the pigtail adapters into the adapter bezel.



Step 6: Place back the cover and plug-in patch cords as needed.





Additional optical fiber bezels including duplex ST, SC, FC & quad LC adapter availble upon request.

